

Goodman Metropolitan District
Landscape Maintenance & Capital Improvement Status Report (06.10.13)











Picture 1: Installation of high water detour signs

Picture 2: Installation of handicap signs (before vs. after)

Picture 3: Slide repair (before vs. after)

Picture 4: Roof arch repair (before vs. after)

Picture 5: Installation of trees

Picture 6: Basket ball hoop and net replacement (before vs. after)

Picture 7: Ball field renovations (before vs. after)

Picture 8: Removal of picnic tables (before vs. after)

Picture 9: Removal of graffiti (basketball court) (before vs. after)